



P.O. Box 1089 Coldspring Tx 77331  
 Website: eastexlabs.com  
 Email: eastexlab@eastex.net  
 Tel: 936 653 3249



Texas A and M AgriLife  
 Texas A & M AgriLife  
 1250 Bay Area Blvd  
 Houston, TX 77058

**LABORATORY ANALYTICAL REPORT**

Project: Tx Coastal Exploration Green

Sample Site:	EG-P4-1	Sample Number:	C3D3480-01		Collector:	KW				
Sample Type:	Composite				Sampled:	04/11/2023 18:27				
Sample Matrix:	Water				Received:	04/12/2023 16:40				
Client Matrix:	Water									
Analyte	Result	Reporting Limit	Units	Nelac Status	Batch	Analyzed	Analyst	Method	Notes	
Ammonia as N	<0.1	0.1	mg/L	A	B3D1852	04/17/2023 09:58	SAC	SM 4500 NH3 G		
Total Phosphorus	<0.0600	0.0600	mg/L	A	B3D2620	04/19/2023 15:57	KJH	EPA 200.7		
TSS	68.2	4.0	mg/L	A	B3D1729	04/13/2023 14:59	WLS	SM 2540 D		

**CORRECTED REPORT**  
**ORIGINAL REPORT**  
 DATE 4/20/23  
 project name



P.O. Box 1089 Coldspring Tx 77331  
 Website: eastexlabs.com  
 Email: eastexlab@eastex.net  
 Tel: 936 653 3249



Texas A and M AgriLife  
 Texas A & M AgriLife  
 1250 Bay Area Blvd  
 Houston, TX 77058

**SM 2540 D - Quality Control**  
**Eastex Environmental Laboratory - Coldspring**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
<b>Batch B3D1729 - No Prep</b>										
<b>Blank (B3D1729-BLK1)</b>				Prepared & Analyzed: 04/13/23						
TSS	ND	1.0	mg/L							
<b>Duplicate (B3D1729-DUP1)</b>				Source: C3D2750-01 Prepared & Analyzed: 04/13/23						
TSS	76.0	1.0	mg/L		80.0			5.13	10	
<b>Batch B3D1852 - No Prep</b>										
<b>Blank (B3D1852-BLK1)</b>				Prepared & Analyzed: 04/17/23						
Ammonia as N	ND	0.1	mg/L							
<b>LCS (B3D1852-BS1)</b>				Prepared & Analyzed: 04/17/23						
Ammonia as N	2.08		mg/L	2.00		104	90-110			
<b>Matrix Spike (B3D1852-MS1)</b>				Source: C3D2676-01 Prepared & Analyzed: 04/17/23						
Ammonia as N	8.8	0.1	mg/L	2.50	6.6	89.6	80-120			
<b>Matrix Spike Dup (B3D1852-MSD1)</b>				Source: C3D2676-01 Prepared & Analyzed: 04/17/23						
Ammonia as N	8.7	0.1	mg/L	2.50	6.6	85.0	80-120	1.31	20	
<b>Batch B3D2620 - EPA 200.7</b>										
<b>Blank (B3D2620-BLK1)</b>				Prepared & Analyzed: 04/19/23						
Total Phosphorus	ND	0.0600	mg/L							
<b>LCS (B3D2620-BS1)</b>				Prepared & Analyzed: 04/19/23						
Total Phosphorus	2.89	0.0600	mg/L	2.52		115	85-115			
<b>Matrix Spike (B3D2620-MS1)</b>				Source: C3D2611-01 Prepared & Analyzed: 04/19/23						
Total Phosphorus	7.38	0.0600	mg/L	2.52	4.67	107	70-130			
<b>Matrix Spike Dup (B3D2620-MSD1)</b>				Source: C3D2611-01 Prepared & Analyzed: 04/19/23						
Total Phosphorus	7.45	0.0600	mg/L	2.52	4.67	110	70-130	1.01	20	

*Mark Bourgeois*

Mark Bourgeois, Special Projects Manager

**Qualifiers**



**EASTEX ENVIRONMENTAL LABORATORY, INC.**

P. O. Box 1089 • Colquhoun, TX 77331 | P. O. Box 631375 • Nacogdoches, TX 75963-1375  
 (840) 525-0508 • FAX (846) 653-3172 | (936) 569-8679 • FAX (936) 569-8951  
 WWW.EASTEXLAB.COM

REPORT TO: AgriLife Extension ADDRESS TO: \_\_\_\_\_

**1 Company**  
AgriLife Extension  
 Address: 1335 Regents Park Suit 260  
Houston, TX 77058  
 Adn. \_\_\_\_\_  
 Phone # \_\_\_\_\_  
 Fax # \_\_\_\_\_

**2 Company**  
 Address \_\_\_\_\_  
 Adn. \_\_\_\_\_  
 Phone # \_\_\_\_\_  
 Fax # \_\_\_\_\_  
 P.O. # \_\_\_\_\_

Sampler's Name (Please Print) Kimberly Walls / Christie Taylor Sampler's Signature Christie Taylor

Project Number 23-27-020 Project Name EG W/ker Quality Baseline

Remarks: Effluent Sample

Order ID	④ Sample ID	⑤		⑥		⑦		S I Z E	T Y P E	P P	
		D	T	D	P	F	T				
	EG-P4-1	4/11/23	1527	C 9.1	175	-	0.5	13.0	OT 1	3 P	C
	L									4 P	5/5
										1 L	5 P
										1 L	5 P
										1 L	5 P

⑧ ANALYSE  
TSS  
Ammonia  
Total Phosphate

Prepared by: Christie Taylor Date: 4/12/23 14:33  
 Received by: Christie Taylor Date: 4/12/23 14:33  
 Preformed by: Christie Taylor Date: \_\_\_\_\_  
 Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Full Name of Christie Taylor Date 4-12-23 Time 1640  
 Lab Use: Other Sample Location: \_\_\_\_\_ Date: 4-12-23 Time: 1640  
 Address: \_\_\_\_\_ Date: \_\_\_\_\_

Chief of Custody: Reidson Z. 03124117 \* Information has not been recorded until signature is actual signature.

SEE BACK FOR INSTRUCTIONS  
 EASTEX ENVIRONMENTAL LABORATORY, INC.

C3D 3480